

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/12/26	MAKE	TADANO	MODEL	TR-250M-6
SERIAL No.	PLATE : FB2956			STAMP : TR255-1481	
HR METER	14972	HR	Odometer	146100	km
TIRE SIZE	385/95R25			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	E/Gヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	FAIR ☒ Attn	A LITTLE ☒ MIDDLE ☐ SEVERE ☐
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	白煙あり WHITE FUMES

OPERATION PUMP	
Sound	FAIR ☒ Attn
Oil leakage	FAIR ☒ Attn
Power	FAIR ☒ Attn

COOLING SYSTEM	
Radiator	FAIR ☒ Attn
Oil Cooler	FAIR ☒ Attn

OPERATING SYSTEM	
Computer	OK ☒ NG ☐
Swing	FAIR ☒ Attn
Travel	FAIR ☒ Attn

TRANSMISSION	
Transmission	FAIR ☒ Attn
No. OF GEARS	4 GEARS
4WD	4WD ☒ 6WD ☐

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN ☐ FAIR ☐ DIRTY ☒
Operator's Seat	FAIR ☒ Attn
Glasses	FAIR ☒ Attn
AirCon	A/C ☒ H/C ☐ H only ☐ C only ☐ None ☐

COMMENT

BOOM	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	FAIR ☒ Attn
DERRICKING CYL.	FAIR ☒ Attn
EXTENSION CYL.	FAIR ☐ Attn ☒ にじみあり OIL OOZING
JIB	YES ☒ NO ☐
JIB TYPE	STD ☐ PWR ☒
MAIN & SUB WIRE	YES ☒ NO ☐
FREE FALL	YES ☒ NO ☐
HOOK	25t, 12t, BALL

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	2
TIRE WEAR	FAIR ☒ WORN ☐ UNEVEN WEAR

COMMENT

OUTRIGGERS	
OUTRIGGERS	X ☐ H ☒
OUTRIGGERS COND.	FAIR ☒ Attn
Oil leakage (JACK CYL.)	FRONT L ☐ R ☐ REAR L ☐ R ☐
Oil leakage (SLIDE CYL.)	FRONT L ☐ R ☐ REAR L ☐ R ☐

COMMENT	
E/G回転数安定しない ENGINE SPEED: UNSTABLE	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。