

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/13	MAKE	CAT	MODEL	312D
SERIAL	CAT0312DCFBJ04629		STAMP	CAT0312DCFBJ04629	
HR METER	3379 / 3381	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N	JKH22583
Oil leakage	☒ FAIR · Attn		
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR · Attn		
Oil	☒ FAIR · Attn		
Exhaust Color	☒ FAIR · Attn		
US EPA	YES · ☒ NO		
MAIN PUMP			
Sound	☒ FAIR · Attn		
Oil leakage	☒ FAIR · Attn		
Power	☒ FAIR · Attn		
COOLING SYSTEM			
Radiator	☒ FAIR · Attn		
Oil Cooler	☒ FAIR · Attn		
OPERATING SYSTEM			
Swing	☒ FAIR · Attn		
Travel	☒ FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · ☒ FAIR ·	DIRTY	
Operator's Seat	☒ FAIR · Attn		
Glasses	☒ FAIR · Attn		
AirCon	☒ A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	☒ FAIR · Attn		
Boom Cylinder	☒ FAIR · Attn		
Arm	☒ FAIR · Attn		
Arm Cylinder	☒ FAIR · Attn		
ATTACHMENT	☒ FAIR · Attn		
BKT Cylinder	☒ FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	☒ YES · NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
バックカメラ不良 BACK MONITOR: MALFUNCTION A/Cベルト鳴きあり A/C BELT: NOISES	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。