INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/3/11	MAKE	CAT	MODEL	D7H
SERIAL	2RG00474		STAMP	2RG00474	
HR METER	1559 HR	SHOE	560G	YEAR	YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL 3306DI S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS・DD	DIFF. STEERING YES・NO
Transmission	FAIR・Attn	
Travel	FAIR・Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・FAIR・DIRTY	
Operator's Seat	FAIR・Attn	破れあり HUGE CUTS
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	
BLADE & CYLINDERS		
BLADE	FAIR・Attn	
CYLD.(R)	FAIR・Attn	
CYLD.(L)	FAIR・Attn	
TILT CYLD	FAIR・Attn	未確認 NOT CHECKED
ANGLE CYLD	FAIR・Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
Ripper	MULTI・S/S	Shanks	2 PCS
Ripper CYLD.	FAIR・Attn		
COMMENT			
ROPS、ブレード未装着 ROPS HEAD GUARD & BLADE: NOT ATTACHED			
HRメーター:1周している？ HR METER: MADE A ROUND?			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。