

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/3/26	MAKE	CAT	MODEL	330FL
SERIAL	CAT0330FELCG10011		STAMP	CAT0330FELCG10011	
HR METER	3122 / 3123	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b> C7.1 <b>S/N</b>	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	<input checked="" type="radio"/> YES · NO
<b>MAIN PUMP</b>	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
<b>OPERATING SYSTEM</b>	
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
<b>INTERIOR See Photos. 写真参照</b>	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
<b>BOOM / ARM / BKT</b>	
Boom	<input checked="" type="radio"/> FAIR · Attn
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn
Arm	<input checked="" type="radio"/> FAIR · Attn
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn
BKT	<input checked="" type="radio"/> FAIR · Attn
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
BKT	<input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER ( )
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。