

INSPECTION SHEET 検品書

TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2026/1/23	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE				
MAKE	TADANO		MODEL	TL-250M-5			
SERIAL	340791		STAMP	NOT FOUND			
HR METER	5713	HR	Odometer	358262	km	YEAR	YR
CHASSIS	MODEL	KC-KS305R	No.	530038	TIRE	11R22.5	

ENGINE(CRANE) : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
ENGINE(CHASSIS) : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	
Swing	FAIR · Attn	
Travel	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	AT · MT	No. OF GEARS 6 GEARS
Transmission	FAIR · Attn	
No. of DRIVE WHEELS	- WD 後輪2デフ	REAR 2 DIFFERENTIALS
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C	H only · C only · NONE

CRANE	
WEIGHT	1
HOOK	25t, BALL
BOOM	
MAIN BOOM	
BOOM TOTAL	
No. of Section	4 SECTIONS
TOP SHEAVE	YES · NO
JIB	STD · PWR
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS	
OUTRIGGERS	FAIR · Attn *1
FRONT JACK	YES · NO
COMMENT	
リフマグ、発電機あり W/LIFTING MAGNET & GENERATOR	
穴あり HOLES	
起伏シリンダー油漏れあり DERRICKING CYLINDER: OIL LEAKING	
*1 モニター表示不良 MONITOR: MALFUNCTION TO DISPLAY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。