

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/1/6	MAKE	HITACHI	MODEL	ZW180-5B		
SERIAL	BANNDBA0TH7420276			STAMP	H74-20276		
HR METER	16821	HR	Odometer	45634	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25		

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
TRANSMISSION & TRAVEL		
T/M TYPE	PS	DD
Transmission	FAIR	Attn
Travel	FAIR	Attn
FOOT BRAKE	FAIR	Attn
PARKING BRAKE	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR · DIRTY
Operator's Seat	FAIR	Attn 破れあり CUT
Glasses	FAIR	Attn
AirCon	A/C	H/C · H only · C only · None
FRONT & CYLINDERS		
Arm	FAIR	Attn
Bell crank	FAIR	Attn
Bucket	FAIR	Attn
Articulate	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
オイルフィルターにじみあり OIL FILTER: OIL Oozing	
! マーク点灯、エラー表示あり WARNING LAMP: ON, ERROR DISPLAY	
E/Gチェックランプ点灯あり CHECK ENGINE LAMP: ON	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。