

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/1/7	MAKE	MAEDA	MODEL	LC785M-6
SERIAL No.	PLATE :	31614	STAMP	31614	
HR METER	3704	HR	SHOE	450G PADS	YEAR YR

ENGINE : MODEL 4D95LE-3 S/N 132211	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
OPERATION PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
OPERATING SYSTEM	
Computer	☒ OK · NG
Swing	☒ FAIR · Attn
Travel	☒ FAIR · Attn
BOOM	
MAIN BOOM	
BOOM TOTAL	
TOP SHEAVE	YES ☒ NO
JIB	
TOWER	

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4	
COMMENT	
WEIGHT	-
HOOK	4.9t
FREE FALL	YES ☒ NO
LIFTER	YES ☒ NO
COMMENT	
5段ブーム 5-SECTION BOOM	
CAB	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。