

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/12/22	MAKE	KATO	MODEL	KRM-13H
SERIAL No.	PLATE : 5911217		STAMP : KR130-1217		
HR METER	17612	HR	Odometer	135362	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	黒煙あり BLACK FUMES

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Computer	OK	NG	
Swing	FAIR	Attrn	ガタあり SWING: LOOSE
Travel	FAIR	Attrn	

TRANSMISSION

Transmission	FAIR • Attn	
No. OF GEARS	4	GEARS
4WD	4WD • 6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn	
DERRICKING CYL.	FAIR	▪ Attn	
EXTENSION CYL.	FAIR	▪ Attn	
JIB	YES	▪ NO	
JIB TYPE	STD	▪ PWR	
MAIN & SUB WIRE	YES	▪ NO	
FREE FALL	YES	▪ NO	
HOOK	13t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	FAIR • WORN • UNEVEN WEAR	

COMMENT

OUTRIGGERS

OUTRIGGERS	X	•	(H)	
OUTRIGGERS COND.	FAIR	•	(Attrn)	
Oil leakage (JACK CYL.)	FRONT	(L)	• R	REAR L • R
Oil leakage (SLIDE CYL.)	FRONT	L	• R	REAR L • R

COMMENT

排気漏れあり EXHAUST LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。