

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/13	MAKE	KOMATSU	MODEL	PC200-10
SERIAL	456467		STAMP	KMT?????????????? MANY LETTERS: UNREADABLE	
HR METER	5624	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		6D107E-2	S/N	26668641
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn	ガタあり SWING: LOOSE		
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn	破れあり HUGE CUTS		
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn			
Arm	FAIR · Attn	ガタあり LOOSE		
Arm Cylinder	FAIR · Attn			
ATTACHMENT	FAIR · Attn			
BKT Cylinder	FAIR · Attn			

UNDERCARRIAGE : See Photos. 写真参照					
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
BKT	STD / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG ▪ WRIST				
Multi	MULTI ▪ 2 ▪ NO				
ARM-CRANE	YES ▪ NO				
BLADE	YES ▪ NO				
OFFSET	YES ▪ NO				
OFFSET Cylinder	FAIR ▪ Attn				
Piping	YES ▪ NO	Breaker only ▪ Multi			
COMMENT					
リペイントあり REPAINTED					
L04システム異常表示出る時あり(検品中2回)					
“L04” ERROR DISPLAY FOR SYSTEM					
(JUST CHECKED TWICE AT THE INSPECTION TIME)					
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。