

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/13	MAKE	CAT	MODEL	313BCR
SERIAL	AEX00794			STAMP	AEX00794
HR METER	11437	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G PADS

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	ホースにじみあり SOME HOSE: OIL OOZING
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	*1
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUT
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	左右油漏れあり CYLINDERS: OIL LEAKING
Arm	FAIR · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
スイベル下周りにじみあり BOTTOM OF SWIVEL: OIL OOZING	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi *2
COMMENT	
ブーム周りホースひび割れあり SOME HOSES AROUND BOOM: CRACKED	
オイルフィルター、バルブ周りにじみあり	
AROUND OIL FILTER & VALVE: OIL OOZING	
燃料フィルターにじみあり FUEL FILTER: OIL OOZING	
左操作レバー周りガタあり BOTTOM OF LEFT OPERATION LEVER: LOOSE	
A/Cベルト欠 A/C: NO BELT	
*1 水に油混入、キャップ破損あり	
*1 OIL MIXED INTO COOLANT, CAP: BROKEN	
*2 ペダル踏んでも油圧起きない	
*2 UNABLE TO SUPPLY ANY HYDRAULIC PRESSURE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。