

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/1/9	MAKE	KOMATSU	MODEL	WA80-3
SERIAL	13272		STAMP	WA053-13272	
HR METER	1447	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	17.5/65-20	

ENGINE : MODEL 4D95LE-3 S/N 125783	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	YES · ☒ NO
OPERATION PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ PS · DD
Transmission	☒ FAIR · Attn
Travel	☒ FAIR · Attn
FOOT BRAKE	☒ FAIR · Attn
PARKING BRAKE	☒ FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	A/C · H/C · ☒ H only · C only · None
FRONT & CYLINDERS	
Arm	☒ FAIR · Attn
Bell crank	☒ FAIR · Attn
Bucket	☒ FAIR · Attn
Articulate	☒ FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES · ☒ NO
ATTACHMENTS	
STD BKT	☒ YES · OTHER
BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO
COMMENT	
両側E/Gフードダンパー不良 ENGINE HOOD DAMPERS: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。