

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

|                 |                                        |      |        |           |        |
|-----------------|----------------------------------------|------|--------|-----------|--------|
| INSPECTION DATE | 2026/1/7                               | MAKE | KUBOTA | MODEL     | U-40-6 |
| SERIAL          | 11011                                  |      | STAMP  | 11011     |        |
| HR METER        | 5923                                   | HR   | YEAR   | YR        |        |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE   | 400G PADS |        |

|                                                |                                        |
|------------------------------------------------|----------------------------------------|
| <b>ENGINE : MODEL</b> V2607 <b>S/N</b> 8DL0300 |                                        |
| Oil leakage                                    | FAIR • Attn                            |
| Blow-By                                        | FAIR • Attn A LITTLE • MIDDLE • SEVERE |
| Sound                                          | FAIR • Attn 異音あり NOISES                |
| Oil                                            | FAIR • Attn                            |
| Exhaust Color                                  | FAIR • Attn                            |
| US EPA                                         | YES • NO                               |
| <b>MAIN PUMP</b>                               |                                        |
| Sound                                          | FAIR • Attn                            |
| Oil leakage                                    | FAIR • Attn                            |
| Power                                          | FAIR • Attn                            |
| <b>COOLING SYSTEM</b>                          |                                        |
| Radiator                                       | FAIR • Attn                            |
| Oil Cooler                                     | FAIR • Attn                            |
| <b>OPERATING SYSTEM</b>                        |                                        |
| Swing                                          | FAIR • Attn                            |
| Travel                                         | FAIR • Attn                            |
| <b>INTERIOR See Photos. 写真参照</b>               |                                        |
| INTERIOR COND.                                 | CLEAN • FAIR • DIRTY                   |
| Operator's Seat                                | FAIR • Attn                            |
| Glasses                                        | FAIR • Attn                            |
| AirCon                                         | A/C • H/C • H only • C only • None     |
| <b>BOOM / ARM / BKT</b>                        |                                        |
| Boom                                           | FAIR • Attn                            |
| Boom Cylinder                                  | FAIR • Attn                            |
| Arm                                            | FAIR • Attn                            |
| Arm Cylinder                                   | FAIR • Attn                            |
| ATTACHMENT                                     | FAIR • Attn ガタ大 MUCH LOOSE             |
| BKT Cylinder                                   | FAIR • Attn                            |

|                                                                      |                               |
|----------------------------------------------------------------------|-------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |                               |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 4                             |
| <b>COMMENT</b>                                                       |                               |
| BKT (STD / SLOPE / NARROW / SKELETON / OTHER ( ))                    |                               |
| Lever                                                                | LONG • WRIST                  |
| Multi                                                                | MULTI • 2 • NO                |
| ARM-CRANE                                                            | YES • NO *1                   |
| BLADE                                                                | YES • NO                      |
| OFFSET                                                               | YES • NO                      |
| OFFSET Cylinder                                                      | FAIR • Attn                   |
| Piping                                                               | YES • NO Breaker only • Multi |
| <b>COMMENT</b>                                                       |                               |
| Hリンク:ガタあり H-LINK: LOOSE                                              |                               |
| 機械プレートとE/GプレートのE/Gナンバーが違う                                            |                               |
| ENGINE NUMBER: NOT EQUAL AT MACHINE PLATE & ENGINE PLATE             |                               |
| *1 システム異常表示あり(モードは入るが一度入れると解除できない)                                   |                               |
| *1 WARNING DISPLAY FOR SYSTEM                                        |                               |
| (CRANE MODE: UNABLE TO TURN OFF AFTER TURNING ON)                    |                               |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                               |
| 4                                                                    |                               |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。