

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/1/7	MAKE	CAT	MODEL	312D
SERIAL	CAT0312DCFBJ00864			STAMP	CAT0312DCFBJ00864
HR METER	6449 / 6455	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL		S/N	JKH06185
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	☒ YES	NO	
MAIN PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
OPERATING SYSTEM			
Swing	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · ☒ FAIR	DIRTY	
Operator's Seat	☒ FAIR	Attn	破れあり TORN
Glasses	☒ FAIR	Attn	
AirCon	☒ A/C	H/C · H only · C only · None	
BOOM / ARM / BKT			
Boom	☒ FAIR	Attn	
Boom Cylinder	FAIR · ☒ Attn	左右油漏れ小	CYLINDERS: OIL LEAKING
Arm	☒ FAIR	Attn	
Arm Cylinder	FAIR · ☒ Attn	にじみあり	OIL OOZING
ATTACHMENT	☒ FAIR	Attn	ガタあり LOOSE
BKT Cylinder	☒ FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
左ピンブッシュ割れあり SOME LEFT PIN BUSH: BROKEN	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	☒ YES · NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
リリーフかけるとエンストする	
ENGINE STALLING WITH ENGINE LOAD INCREASING	
走行中エアフィルタ目詰まり表示あり、止まると消える	
WARNING DISPLAY FOR AIR FILTER CLOGGING DURING TRAVELING	
(THE WARNING DISPLAY: DISAPPEARING WHEN NOT TRAVELING)	
リペイントあり REPAINTED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。