

INSPECTION SHEET 檢品書  
GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE	2026/1/16	CATEGORY	GENERATOR	COMPRESSOR / WELDER
MAKE	DENYO	MODEL	DCA-220ESM	
SERIAL	3807687	STAMP	NOT FOUND	
HR METER	UNKNOWN	HR	TIRE SIZE	YEAR YR

ENGINE :	MODEL	6D24	S/N	406931
Oil leakage	<input checked="" type="radio"/> FAIR • Attn		Oil	<input checked="" type="radio"/> FAIR • Attn
Blow-By	<input checked="" type="radio"/> FAIR • Attn	A LITTLE • MIDDLE • SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR • Attn
Sound	<input checked="" type="radio"/> FAIR • Attn		Radiator	<input checked="" type="radio"/> FAIR • Attn

GENERATOR			
RATED POWER	200 / 220	KVA	Leaking Breaker Condition <input checked="" type="radio"/> • Attn
RATED AMPERE	577 / 289	A	Insulation Condition <input checked="" type="radio"/> • Attn
Output Terminal	<input checked="" type="radio"/> • Attn		

COMPRESSOR					
RATED PRESSURE		Mpa Kg/cm2	Unload Condition	FAIR	▪ Attn
RATED AIR FLOW		m3/min	Receiver Tank Condition	FAIR	▪ Attn
Compressor Oil Leak	FAIR	▪ Attn	Safety Valve Condition	FAIR	▪ Attn

CONDITION	FAIR	Attn
パネルセレクトボタン反応しない、HR等表示不可 MONITOR SELECT BUTTON: NOT WORKING, UNABLE TO SWITCH TO HR METER or ANYTHING		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。