

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2026/1/13	MAKE	HITACHI	MODEL	ZX125W
SERIAL	HCM11P00C00006009			STAMP	HCM11P00C00006009
HR METER	7865	HR	Odometer	26882	km
CAB/CNP	ROPS CAB / CAB / ROPS	CNP / CNP / NONE	TIRE SIZE	9.00-20	

ENGINE : MODEL	S/N
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn 黒煙小 A LITTLE BLACK FUMES
US EPA	YES · NO

MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

OPERATING SYSTEM		
Swing	FAIR・Attn	ガタあり SWING: LOOSE
Travel	FAIR・Attn	

INTERIOR	See Photos. 写真参照
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 破れあり CUTS
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · Attn	油漏れあり OIL LEAKING
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	油漏れあり OIL LEAKING

UNDERCARRIAGE :	See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR

COMMENT		
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG • (WRIST)	
Multi	(MULTI) • 2 • NO	
ARM-CRANE	YES • (NO)	
BLADE	(YES) • NO	
OFFSET	YES • (NO)	
OFFSET Cylinder	FAIR • Attn	
Piping	(YES) • NO	Breaker only • Multi *1
OUTRIGGERS COND.	FAIR • Attn	

COMMENT	
ブーム周りホースひび割れあり SOME HOSES AROUND BOOM: CRACKED	
コントロールバルブ油漏れ小 CONTROL VALVE: OIL LEAKING	
Mマークランプ点灯、ブザー音あり	
MAINTENANCE LAMP & WARNING SOUNDS: ON	
アクセルダイヤル不良 ACCELERATOR KNOB: MALFUNCTION	
A/Cベルト鳴きあり A/C BELT: NOISES	
*1 油圧起きない UNABLE TO SUPPLY ANY HYDRAULIC PRESSURE	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。