

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/20	MAKE	KATO	MODEL	KR-25H-V7
SERIAL No.	PLATE :	5110303	STAMP :	KRC005-0303	
HR METER	14669	HR	Odometer	59168	km
TIRE SIZE	385/95R25		YEAR		YR

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	下部にじみあり BOTTOM OF ENGINE: OIL OOZING
Blow-By	☒ FAIR ☐ Attn	A LITTLE ☐ MIDDLE ☐ SEVERE
Sound	☒ FAIR ☐ Attn	
Oil	☒ FAIR ☐ Attn	
Exhaust Color	☒ FAIR ☐ Attn	

OPERATION PUMP

Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM

Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

OPERATING SYSTEM

Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION

Transmission	FAIR • Attn
No. OF GEARS	4
4WD	4WD • 6WD

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	•	FAIR	•	DIRTY
----------------	-------	---	------	---	-------

Operator's Seat	FAIR • Attn
Glasses	FAIR • Attn

AirCon	A/C	H/C	H only	C only	None
--------	------------	-----	--------	--------	------

COMMENT

BOOM

No. of Section	4	SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn	
DERRICKING CYL.	FAIR	▪ Attn	
EXTENSION CYL.	FAIR	▪ Attn	
JIB	YES	▪ NO	
JIB TYPE	STD	▪ PWR	
MAIN & SUB WIRE	YES	▪ NO	
FREE FALL	YES	▪ NO	
HOOK	25t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	1
---	---

TIRE WEAR	FAIR • WORN • UNEVEN WEAR
-----------	---------------------------

COMMENT

OUTRIGGERS

OUTRIGGERS	X · (H)
------------	---------

OUTRIGGERS COND.	FAIR	▪	Attn		
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L ▪ R

COMMENT

穴あり BODY: HUGE HOLES

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
---	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。