

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/8	MAKE	KOMATSU	MODEL	PC120-8
SERIAL	82268		STAMP	KMTPC202C01082268	
HR METER	9290	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL		S/N	509964
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE *1	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn	ガタあり SWING: LOOSE	
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn	破れあり CUT	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn	左右油漏れあり CYLINDERS: OIL LEAKING	
Arm	FAIR · Attn	ガタあり LOOSE	
Arm Cylinder	FAIR · Attn		
ATTACHMENT	FAIR · Attn	ガタあり LOOSE	
BKT Cylinder	FAIR · Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT			
シューパッドカスが付いているだけ RUBBER PADS: ALMOST GONE			
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()		
Lever	LONG ▪ (WRIST)		
Multi	MULTI ▪ 2 ▪ (NO)		
ARM-CRANE	YES ▪ (NO)		
BLADE	YES ▪ (NO)		
OFFSET	YES ▪ (NO)		
OFFSET Cylinder	FAIR ▪ Attn		
Piping	YES ▪ (NO)	Breaker only ▪ Multi	
COMMENT			
ブーム周りホースヒビあり			
HOSES AROUND LOWER PART OF BOOM: CRACKED			
E/Gフードヒンジ破損あり SOME ENGINE HOOD HINGE: BROKEN			
*1 オイル吐出しあり OIL SPURTING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。