

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/27	MAKE	HITACHI	MODEL	ZX10U-2
SERIAL	HCM1MP00J00012365		STAMP	HCM1MP00J00012365	
HR METER	1510	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	180R	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	ガタあり SWING: LOOSE
Travel	(FAIR) · Attn	*1
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	ガタ、破れあり LOOSE, CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
BOOM / ARM / BKT		
Boom	(FAIR) · Attn	
Boom Cylinder	(FAIR) · Attn	
Arm	(FAIR) · Attn	
Arm Cylinder	(FAIR) · Attn	
ATTACHMENT	(FAIR) · Attn	ガタあり LOOSE
BKT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT クローラ伸縮OK VARIABLE WIDTH UNDERCARRIAGE		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · (WRIST)	
Multi	MULTI · 2 · (NO)	
ARM-CRANE	YES · (NO)	
BLADE	(YES) · NO	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	(YES) · NO Breaker only · (Multi)	
COMMENT スイングガタあり、ペダル戻り悪い SWING PART: LOOSE, SWING PEDAL: HARD TO RETURN *1 HI/LO切替できない、HIのまま *1 HI/LO SWITCH: MALFUNCTION (ALWAYS HIGH SPEED)		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。