

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/26	MAKE	KOMATSU	MODEL	PC35MR-2
SERIAL	6856	STAMP	KMTPC096H05006856		
HR METER	UNKNOWN	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE		SHOE	300G	

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	<u>YES</u> · NO	
MAIN PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> · Attn	ガタあり SWING: LOOSE
Travel	<u>FAIR</u> · Attn	HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	
Operator's Seat	<u>FAIR</u> · Attn	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	
BOOM / ARM / BKT		
Boom	<u>FAIR</u> · Attn	
Boom Cylinder	FAIR · <u>Attn</u>	*1
Arm	<u>FAIR</u> · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · <u>Attn</u>	油漏れ小 OIL LEAKING
ATTACHMENT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
左右アイドル周り曲がりあり	
TRACKS AROUND IDLERS: A LITTLE BENT TO INSIDE	
クローラ伸縮OK VARIABLE WIDTH UNDERCARRIAGE	
BKT	STD / SLOPE / NARROW / SKELETON <u>OTHER</u> (FORK GRAB)
Lever	LONG · <u>WRIST</u>
Multi	MULTI · 2 · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	<u>YES</u> · NO Breaker only · Multi 5
COMMENT	
リペイントあり REPAINTED	
安全レバー不良、コネクター抜き挿しで解除可	
SAFETY LEVER: MALFUNCTION	
(ABLE TO LOCK or RELEASE	
BY REMOVING or INSERTING THE CONNECTOR)	
HRメーター、メーター不良 HR METER & INDICATOR: MALFUNCTION	
スイング部ガタあり SWING PART: LOOSE	
*1 2ピースブーム、2段目シリンダー油漏れ小、根本側メッキ剥がれあり	
*1 2-PIECE BOOM (LENGTH: 5.6m),	
2nd CYLINDER: OIL LEAKING,	
BOTTOM CYLINDER: COATING PEELED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。