

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |             |
|-----------------|----------------------------------------|------|---------|-------------------|-------------|
| INSPECTION DATE | 2026/1/26                              | MAKE | HITACHI | MODEL             | ZX350LCK-5B |
| SERIAL          | HCMDDDA5C00071147                      |      | STAMP   | HCMDDDA5C00071147 |             |
| HR METER        | 8650                                   | HR   | YEAR    | YR                |             |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 800G              |             |

|                           |                                    |                            |
|---------------------------|------------------------------------|----------------------------|
| ENGINE : MODEL            |                                    | S/N                        |
| Oil leakage               | FAIR · Attn                        |                            |
| Blow-By                   | FAIR · Attn                        | A LITTLE · MIDDLE · SEVERE |
| Sound                     | FAIR · Attn                        |                            |
| Oil                       | FAIR · Attn                        |                            |
| Exhaust Color             | FAIR · Attn                        |                            |
| US EPA                    | YES · NO                           |                            |
| MAIN PUMP                 |                                    |                            |
| Sound                     | FAIR · Attn                        |                            |
| Oil leakage               | FAIR · Attn                        |                            |
| Power                     | FAIR · Attn                        |                            |
| COOLING SYSTEM            |                                    |                            |
| Radiator                  | FAIR · Attn                        |                            |
| Oil Cooler                | FAIR · Attn                        |                            |
| OPERATING SYSTEM          |                                    |                            |
| Swing                     | FAIR · Attn                        |                            |
| Travel                    | FAIR · Attn                        |                            |
| INTERIOR See Photos. 写真参照 |                                    |                            |
| INTERIOR COND.            | CLEAN · FAIR · DIRTY               |                            |
| Operator's Seat           | FAIR · Attn                        | 破れ大 TORN                   |
| Glasses                   | FAIR · Attn                        |                            |
| AirCon                    | A/C · H/C · H only · C only · None |                            |
| BOOM / ARM / BKT          |                                    |                            |
| Boom                      | FAIR · Attn                        |                            |
| Boom Cylinder             | FAIR · Attn                        |                            |
| Arm                       | FAIR · Attn                        |                            |
| Arm Cylinder              | FAIR · Attn                        |                            |
| ATTACHMENT                | FAIR · Attn                        |                            |
| BKT Cylinder              | FAIR · Attn                        | 油漏れ小 OIL LEAKING           |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。