

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/9	MAKE	KOBELCO	MODEL	SK100
SERIAL	YW-08966			STAMP	YW-08966
HR METER	10229	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G PADS

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • NO	
MAIN PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Swing	FAIR • Attn	ゴリゴリ感、ガタあり RATTLING, SWING: LOOSE
Travel	FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	破れ大 TORN
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	FAIR • Attn	
Boom Cylinder	FAIR • Attn	
Arm	FAIR • Attn	ガタあり LOOSE
Arm Cylinder	FAIR • Attn	
ATTACHMENT	FAIR • Attn	ガタあり LOOSE
BKT Cylinder	FAIR • Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
旋回モーター下にじみあり BOTTOM OF SWING MOTOR: OIL OOZING 右トラックローラーガタあり SOME RIGHT TRACK ROLLERS: LOOSE	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi *1
COMMENT	
ブーム背面ホースひび割れあり SOME HOSES AROUND BOOM: CRACKED モニター表示不良 MONITOR: NOT DISPLAYING ブザー音あり(モニター見えないため原因不明) WARNING SOUNDS: ON (REASON: UNKNOWN DUE TO MONITOR DOES NOT DISPLAY) A/Cベルト緩い A/C BELT: LOOSE *1 S/W固着あり、油圧掛かったまま戻らない *1 PIPING SWITCH UNDER PEDAL: STUCK (ALWAYS SUPPLYING SOME HYDRAULIC PRESSURE)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。