

INSPECTION SHEET 検品書
MOTOR GRADER グレーダー

INSPECTION DATE	2026/1/13	MAKE	MITSUBISHI	MODEL	MG300
SERIAL	3G000798			STAMP	3G000798
HR METER	E5335	HR	Odometer	43077	km
YEAR	YR				
SCARIFIER	YES	NO	3	BLADE	3400 mm
CAB/CNP	CAB	CNP	NONE	TIRE SIZE	12.00-24

ENGINE : MODEL	S/N	200912
Oil leakage	FAIR	Attn *1
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
TRANSMISSION & TRAVEL		
T/M TYPE	PS	DD
Transmission	FAIR	Attn
Travel	FAIR	Attn
FOOT BRAKE	FAIR	Attn
PARKING BRAKE	FAIR	Attn 効かない MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR · DIRTY
Operator's Seat	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C · H only · C only · None
HYD. CYLINDER		
For Blade	FAIR	Attn
For Scarifier	FAIR	Attn
Articulate	FAIR	Attn *2

UNDERCARRIAGE :	See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
ステアリングシリンダーにじみあり STEERING CYLINDER: OIL OOZING	
サークルモーター下油漏れ小	
BOTTOM OF CIRCLE DRIVE MOTOR: OIL LEAKING	
ミッション下ドレーン周りにじみあり	
AROUND DRAIN UNDER TRANSMISSION: OIL OOZING	
オイルゲージ破損あり、緩い OIL GAUGE: BROKEN, LOOSE	
サークルスイング用シリンダーにじみあり	
CIRCLE SWING CYLINDER: OIL OOZING	
HRメーターストップ HR METER: STOPPED	
燃料メーター不良 FUEL GAUGE: MALFUNCTION	
*1 ブロック周りにじみあり AROUND ENGINE BLOCK: OIL OOZING	
*2 左側にじみ、右側油漏れあり	
*2 LEFT CYLINDER: OIL OOZING, RIGHT CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。