

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/19	MAKE	CAT	MODEL	345D
SERIAL	CAT0345DTFES00??? SOME LETTERS: UNKNOWN		STAMP	CAT0345DTFES00170	
HR METER	2471 / 2473	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		C13	S/N	TXF01643
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	擦れあり WORN	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	右側油漏れ小 RIGHT CYLINDER: OIL LEAKING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi 4
COMMENT	
プレート切れあり PLATE: PARTLY BROKEN	
ブーム背面ホース破れあり	
SOME HOSES AROUND BOOM: A LITTLE DAMAGED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。