

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/24	MAKE	HITACHI	MODEL	ZX670LCH-3
SERIAL	NO PLATE			STAMP	HCM1J800C00020031
HR METER	20255			YEAR	YR
CAB/CNP	ROPS CAB <input checked="" type="checkbox"/> CAB <input type="checkbox"/> ROPS CNP / CNP / NONE			SHOE	650G

ENGINE : MODEL 6WG1 S/N 605007			UNDERCARRIAGE : See Photos. 写真参照				
Oil leakage	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>	オイルパン周りにじみあり AROUND OIL PAN: OIL Oozing	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3			
Blow-By	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>	A LITTLE <input checked="" type="checkbox"/> MIDDLE <input type="checkbox"/> SEVERE	COMMENT				
Sound	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		スイベル下周り油漏れあり BOTTOM OF SWIVEL: OIL LEAKING				
Oil	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		右Fキャリアローラー欠 FRONT RIGHT CARRIER ROLLER: MISSING				
Exhaust Color	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		エレベータCAB ELEVATOR CAB				
US EPA	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		作動油タンクホース油漏れ小 HYDRAULIC OIL TANK HOSE: OIL LEAKING				
MAIN PUMP			BKT	STD / SLOPE / NARROW / SKELETON <input checked="" type="checkbox"/> OTHER (MAGNET)			
Sound	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		Lever	LONG <input type="checkbox"/> WRIST <input checked="" type="checkbox"/>			
Oil leakage	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>	ポンプ、ホースにじみあり PUMP & SOME HOSES: OIL Oozing	Multi	MULTI <input type="checkbox"/> 2 <input checked="" type="checkbox"/> NO <input type="checkbox"/>			
Power	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		ARM-CRANE	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>			
COOLING SYSTEM			BLADE	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>			
Radiator	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		OFFSET	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>			
Oil Cooler	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		OFFSET Cylinder	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>			
OPERATING SYSTEM			Piping	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> Breaker only <input type="checkbox"/> Multi			
Swing	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>	ガタあり SWING: LOOSE	COMMENT				
Travel	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		走行していると少しづつ旋回する(振動?) A LITTLE SWINGING DURING TRAVELING (BY VIBRATION?)				
INTERIOR See Photos. 写真参照			旋回モーター周り、コントロールバルブ油汚れあり				
INTERIOR COND.	CLEAN <input type="checkbox"/> FAIR <input checked="" type="checkbox"/> DIRTY <input type="checkbox"/>		AROUND SWING MOTOR & CONTROL VALVE: OIL STAINS				
Operator's Seat	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		発電機あり(繋がっていない)				
Glasses	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		W/GENERATOR MAKE: DENYO DCA-60ESI-3758194 (NOT CONNECTING)				
AirCon	A/C <input type="checkbox"/> H/C <input type="checkbox"/> H only <input type="checkbox"/> C only <input type="checkbox"/> None <input checked="" type="checkbox"/>		発電機:E/Gオイル漏れあり、ラジエータ水漏れ大、水、E/Gオイル少ない、E/G始動不可				
BOOM / ARM / BKT			GENERATOR: ENGINE OIL LEAKING, SEVERE COOLANT LEAKING,				
Boom	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1		COOLANT LEVEL & ENGINE OIL LEVEL: NOT ENOUGH,				
Boom Cylinder	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		UNABLE TO START THE ENGINE				
Arm	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		付属品:部材一式 SOME PARTS AS SPARE				
Arm Cylinder	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>	油漏れ小 OIL LEAKING	*1 ホースにじみ、左側プラケット曲がり、ブッシュ外れあり				
ATTACHMENT	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>	動作未確認 OPERATION: NOT CHECKED	*1 SOME HOSE: OIL Oozing, LEFT BRACKET: DISTORTED, BUSH: COME OFF				
BKT Cylinder	FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/>		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				
					3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。