

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/1/13	CATEGORY	自走式スクリーン MOBILE SCREEN		
MAKE	MAEDA		MODEL	BM545S-1A	
SERIAL	1188		STAMP	1188	
HR METER	3549	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP <u>NONE</u>		SHOE	450G	TIRE

ENGINE	MODEL	S/N
Oil leakage	<u>FAIR</u> ・ Attn	Oil
Blow-By	<u>FAIR</u> ・ Attn	Exhaust Color
Sound	<u>FAIR</u> ・ Attn	EPA

CONDITION	<u>FAIR</u> ・ Attn	
コンベア格納シリンダー左側油漏れ小 LEFT FOLDING CONVEYOR: OIL LEAKING		

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR
COMMENT			
ファンベルト鳴きあり FAN BELT: NOISES			
付属品: リモコン(機械の中にあり) REMOTE CONTROL			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。