

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/22	MAKE	HITACHI	MODEL	ZX480LCK-3
SERIAL	HCM1JP00E00024176			STAMP	HCM1JP00E00024176
HR METER	11255	HR	YEAR	2011	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR
Operator's Seat	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C H only C only None
BOOM / ARM / BKT		
Boom	FAIR	Attn
Boom Cylinder	FAIR	Attn
Arm	FAIR	Attn
Arm Cylinder	FAIR	Attn
ATTACHMENT	FAIR	Attn
BKT Cylinder	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
スイベル下油漏れあり BOTTOM OF SWIVEL: OIL LEAKING	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG WRIST
Multi	MULTI 2 NO
ARM-CRANE	YES NO
BLADE	YES NO
OFFSET	YES NO
OFFSET Cylinder	FAIR Attn
Piping	YES NO Breaker only Multi 3
COMMENT	
ポンプ周りホース油漏れ小 SOME HOSE AROUND PUMP: OIL LEAKING	
アタッチメントなし WITHOUT ATTACHMENT	
HRメータ交換あり HR METER REPLACED	
付属品: 3段ブーム、中間ブーム	
3-SECTION BOOM & INSERT BOOM AS SPARE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。