

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/1/13	MAKE	TCM	MODEL	E180		
SERIAL	88300104		STAMP	M04-00104			
HR METER	5702	HR	Odometer	—	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	23.5-25			

ENGINE :	MODEL	S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	
Transmission	FAIR · Attn	*1
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり HUGE CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
FRONT & CYLINDERS		
Arm	FAIR · Attn	*2
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	*3
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	(FAIR) · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE	(WHEEL STEERING) / COMMAND STEERING / LEVER STEERING
RIDE CONTROL	YES · (NO)
ATTACHMENTS	
STD BKT	YES · (OTHER) スノーブレード SNOW BLADE
BLADE	YES · (NO) Piping for Tilt (YES) · NO
COMMENT	
左サイドカバー変形あり LEFT SIDE COVER: DEFORMED	
*1 2速に入れると前に出ない(滑ってる?)	
*1 2nd GEAR: UNABLE TO TRAVEL FORWARD (SLIPPING?)	
*2 左チルトシリンダーにじみあり LEFT TILT CYLINDER: OIL OOZING	
*3 左右アングルシリンダー、左右バケットシリンダー、 スライドシリンダー油漏れあり	
*3 ANGLE CYLINDERS, BUCKET CYLINDERS, & SLIDE CYLINDER:	
OIL LEAKING	
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。