

**INSPECTION SHEET 検品書**  
**CARRY DUMP キャリーダンプ**

INSPECTION DATE	2026/1/14		MAKE	IHI		MODEL	IC120	
SERIAL	CB003151			STAMP	CB003151			
HR METER	4158	HR	Odometer		km	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	750R		TIRE	
<b>ENGINE : MODEL</b> S/N 73666964				<b>MAIN FRAME</b>				
Oil leakage	FAIR	Attn			MAIN FLAME	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE		<b>VESSEL</b>			
Sound	FAIR	Attn			VESSEL	FAIR	Attn	
Oil	FAIR	Attn			REAR GATE TYPE	NORMAL		L-GATE (FLAT)
Exhaust Color	FAIR	Attn			REAR GATE	FAIR	Attn	
US EPA	YES	NO			<b>UNDERCARRIAGE: See Photos. 写真参照</b>			
<b>OPERATION PUMP</b>					RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4			
Sound	FAIR	Attn			TIRE WEAR	FAIR · WORN · UNEVEN WEAR		
Oil leakage	FAIR	Attn			<b>COMMENT</b>			
Power	FAIR	Attn			E/Gチェックランプ点灯する時あり(検品中1回)			
<b>COOLING SYSTEM</b>					CHECK ENGINE LAMP: ON			
Radiator	FAIR	Attn			(JUST CHECKED ONCE AT THE INSPECTION TIME)			
Oil Cooler	FAIR	Attn						
<b>TRANSMISSION &amp; TRAVEL</b>								
T/M TYPE	PS	DD	No. OF GEARS	2 GEARS				
Transmission	FAIR	Attn						
Travel	FAIR	Attn						
Swing	FAIR	Attn						
Articulate	FAIR	Attn						
FOOT BRAKE	FAIR	Attn						
PARKING BRAKE	FAIR	Attn						
<b>INTERIOR See Photos. 写真参照</b>								
INTERIOR COND.	CLEAN	· FAIR	· DIRTY					
Operator's Seat	FAIR	Attn						
Glasses	FAIR	Attn						
AirCon	A/C	· H/C	· H only	· C only	· None			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。