

**INSPECTION SHEET 検品書**  
**CARRY DUMP キャリーダンプ**

INSPECTION DATE	2026/1/15		MAKE	CAT		MODEL	LD1000E	
SERIAL	CB100243			STAMP	CB100243			
HR METER	8622	HR	Odometer		km	YEAR	YR	
CAB/CNP	ROPS CAB / CAB	ROPS CNP / CNP / NONE		SHOE	750R	TIRE		
<b>ENGINE : MODEL</b> 6HK1 <b>S/N</b> 505947				<b>MAIN FRAME</b>				
Oil leakage	FAIR	Attn			MAIN FLAME	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE		<b>VESSEL</b>			
Sound	FAIR	Attn			VESSEL	FAIR	Attn	
Oil	FAIR	Attn			REAR GATE TYPE	NORMAL · L-GATE (FLAT)		
Exhaust Color	FAIR	Attn			REAR GATE	FAIR	Attn	
US EPA	YES	NO			<b>UNDERCARRIAGE: See Photos. 写真参照</b>			
<b>OPERATION PUMP</b>					RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3			
Sound	FAIR	Attn			TIRE WEAR	FAIR · WORN · UNEVEN WEAR		
Oil leakage	FAIR	Attn			<b>COMMENT</b>			
Power	FAIR	Attn			リペイントあり REPAINTED			
<b>COOLING SYSTEM</b>								
Radiator	FAIR	Attn						
Oil Cooler	FAIR	Attn						
<b>TRANSMISSION &amp; TRAVEL</b>								
T/M TYPE	PS	DD	No. OF GEARS	2 GEARS				
Transmission	FAIR	Attn						
Travel	FAIR	Attn						
Swing	FAIR	Attn						
Articulate	FAIR	Attn						
FOOT BRAKE	FAIR	Attn						
PARKING BRAKE	FAIR	Attn						
<b>INTERIOR See Photos. 写真参照</b>								
INTERIOR COND.	CLEAN	FAIR	DIRTY					
Operator's Seat	FAIR	Attn						
Glasses	FAIR	Attn						
AirCon	A/C	H/C	H only	C only	None	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。