

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/14	MAKE	SUMITOMO	MODEL	SH200-7
SERIAL	SMT200A7A00BH4562		STAMP	SMT200A7A00BH4562	
HR METER	1084	HR	YEAR	YR	
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	790G	

ENGINE : MODEL 4HK1		S/N 865691	
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	☒ YES	NO	
MAIN PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
OPERATING SYSTEM			
Swing	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	☒ CLEAN	FAIR · DIRTY	
Operator's Seat	☒ FAIR	Attn	
Glasses	☒ FAIR	Attn	
AirCon	☒ A/C	H/C · H only · C only · None	
BOOM / ARM / BKT			
Boom	☒ FAIR	Attn	
Boom Cylinder	☒ FAIR	Attn	
Arm	☒ FAIR	Attn	
Arm Cylinder	☒ FAIR	Attn	
ATTACHMENT	☒ FAIR	Attn	
BKT Cylinder	☒ FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	MULTI · ☒ 2 · NO
ARM-CRANE	YES · ☒ NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。