

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/21	MAKE	KATO	MODEL	KR-25H-V5
SERIAL No.	PLATE : 5412262		STAMP : KR258-2262		
HR METER	27094	HR	Odometer	91212	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR - Attn	
Oil Cooler	FAIR - Attn	

OPERATING SYSTEM		
Computer	OK・NG	画面映り悪い MONITOR: BLURRED
Swing	FAIR・Attn	
Travel	FAIR・Attn	

TRANSMISSION		
Transmission	FAIR • Attn	
No. OF GEARS	4	GEARS
4WD	4WD • 6WD	

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY	
Operator's Seat	FAIR ・ Attn	穴あり HOLE
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・ None	

COMMENT

.....

.....

.....

BOOM		
No. of Section	4	SECTIONS
CRACK/ENFORCEMENT	☐ FAIR ▪ Attn	
DERRICKING CYL.	☐ FAIR ▪ Attn	
EXTENSION CYL.	☐ FAIR ▪ Attn	
JIB	☐ YES ▪ NO	
JIB TYPE	STD ▪ ☐ PWR	
MAIN & SUB WIRE	☐ YES ▪ NO	
FREE FALL	☐ YES ▪ NO	
HOOK	25t, BALL	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	2
TIRE WEAR	FAIR • WORN UNEVEN WEAR

COMMENT	

OUTRIGGERS				
OUTRIGGERS	X	•	H	
OUTRIGGERS COND.	FAIR	•	Attn	
Oil leakage (JACK CYL.)	FRONT	L	• R	REAR L • R
Oil leakage (SLIDE CYL.)	FRONT	L	• R	REAR L • R

COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。