

INSPECTION SHEET 検品書
CRAWLER DRILL クローラドリル

INSPECTION DATE	2026/1/20	MAKE	ATLAS COPCO	MODEL	T25DC
SERIAL	V024032BE			STAMP	V024032BE
HR METER	E2129	HR	YEAR	2014	YR
CAB/CNP	CAB / CNP / NONE	SHOE	330G		
DRIFTER MODEL	K0P1540-1351511				

ENGINE : MODEL		S/N	73594145
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn		
Travel	FAIR · Attn	HI/LOスイッチ不良 HI/LO SWITCH: MALFUNCTION	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn	破れあり HUGE CUTS	
Glasses	FAIR · Attn	*1	
AirCon	A/C · H/C · H only · C only · None		
DRIFTER HYDR.			
Lift	FAIR · Attn		
Swing	FAIR · Attn		
Tilt	FAIR · Attn		
Slide	FAIR · Attn	*2	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT 左側オシレーションシリンダーメッキ剥がれ、右側にじみあり LEFT OSCILLATING CYLINDER: COATING PEELED, RIGHT OSCILLATING CYLINDER: OIL OOZING	
Guide(Slide Length)	1280 mm
Rod Changer YES・NO	
Drifter YES・NO	
Compressor YES・NO	
Blow YES・NO	
COMMENT HRメーターストップ HR METER: STOPPED *1 F、上部割れあり WINDSHIELD & SKYLIGHT: CRACKED *2 油漏れ小、メッキ剥がれあり OIL LEAKING, COATING: PEELED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。