

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/14	MAKE	HITACHI	MODEL	ZX225USR
SERIAL	HCM1GD00K00115984			STAMP	HCM1GD00K00115984
HR METER	23167	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600FLAT

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • NO	
MAIN PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	油漏れ小 OIL LEAKING
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Swing	FAIR • Attn	ガタあり SWING: LOOSE
Travel	FAIR • Attn	HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	破れあり TORN
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	FAIR • Attn	
Boom Cylinder	FAIR • Attn	
Arm	FAIR • Attn	ガタあり LOOSE
Arm Cylinder	FAIR • Attn	油漏れ小 OIL LEAKING
ATTACHMENT	FAIR • Attn	*1
BKT Cylinder	FAIR • Attn	油漏れあり OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON (OTHER)
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi 5
COMMENT	
アタッチメント: 回転式カッター ATTACHMENT: ROTATABLE CUTTER	
MAKE: HITACHI S-CC70-80-3-U-2089	
オイルフィルター油漏れ小 OIL FILTER: OIL LEAKING	
クランプアーム付(左右シリンダー油漏れあり)	
W/CLAMP ARM (CYLINDERS: OIL LEAKING)	
A/Cベルト欠 A/C: NO BELT	
*1 開閉用シリンダー油漏れ小 JAW CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。