

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/1/21	MAKE	TADANO	MODEL	BT-200-2
SERIAL No.	PLATE : HB5502			STAMP : NOT FOUND	
HR METER	1993	HR	Odometer	46438	km
YEAR	YR				
CHASSIS	MODEL BDG-XZU404X			No. XZU404-1003418	
SHOE				TIRE SIZE	215/70R17.5
MAX HIGHT	7.0			m	
MAX WEIGHT				200	kg

ENGINE : MODEL N04C S/N	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	YES ☒ NO
OPERATION PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	AT ☒ MT
No. OF GEARS	6 GEARS
Transmission	☒ FAIR · Attn
4WD	4WD ☒ 2WD
Travel	☒ FAIR · Attn
Swing	☒ FAIR · Attn
FOOT BRAKE	☒ FAIR · Attn
PARKING BRAKE	☒ FAIR · Attn
BOOM	
No. of Section	— SECTIONS *1
DERRICKING CYL.	☒ FAIR · Attn
EXTENSION CYL.	☒ FAIR · Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS X · ☒ H OUTRIGGERS COND. ☒ FAIR · Attn	
COMMENT	
橋梁点検車 BRIDGE CHECKER 発電機あり(始動OK、油脂類OK) W/GENERATOR MAKE: SHIN DAIWA EG25M-EB-G00655001925 (ABLE TO START THE ENGINE, OIL: OK) スペアタイヤあり W/SPARE TIRE *1 横(LATERAL): 2-SECTION, 縦(VERTICAL): 5-SECTION, デッキ(DECK): 3-SECTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。