

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/21	MAKE	CAT	MODEL	313-07A
SERIAL	CAT00313CJHR00213		STAMP	CAT00313CJHR00213	
HR METER	8980	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL		S/N	J3623226
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn	右側油漏れ小 RIGHT CYLINDER: OIL LEAKING	
Arm	FAIR · Attn		
Arm Cylinder	FAIR · Attn	油漏れあり OIL LEAKING	
ATTACHMENT	FAIR · Attn		
BKT Cylinder	FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照

RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)3

COMMENT
シューパッド摩耗大、剥がれ多数あり RUBBER PADS: ALMOST GONE

BKT	STD / SLOPE / NARROW / SKELETON / OTHER()		
Lever	LONG ▪ WRIST		
Multi	MULTI ▪ 2 ▪ NO		
ARM-CRANE	YES ▪ NO		
BLADE	YES ▪ NO		
OFFSET	YES ▪ NO		
OFFSET Cylinder	FAIR ▪ Attn		
Piping	YES ▪ NO	Breaker only ▪ Multi	*1

COMMENT
アタッチメントなし WITHOUT ATTACHMENT
*1 左側メクラ欠 LEFT CAP: MISSING

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。