

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/22	MAKE	TADANO	MODEL	GR-500N-2
SERIAL No.	PLATE : 583255			STAMP : T011-0055	
HR METER	21592	HR	Odometer	13932	km
TIRE SIZE	385/95R25			YEAR	2015 YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
TRANSMISSION		
Transmission	☒ FAIR · Attn	
No. OF GEARS	4 GEARS	
4WD	☒ 4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · Attn	
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
COMMENT		
運転席ドア穴開補修跡あり DOOR: REPAIRED		

BOOM					
No. of Section	5	SECTIONS			
CRACK/ENFORCEMENT	☒ FAIR · Attn				
DERRICKING CYL.	☒ FAIR · Attn				
EXTENSION CYL.	☒ FAIR · Attn				
JIB	☒ YES · NO				
JIB TYPE	STD · ☒ PWR				
MAIN & SUB WIRE	☒ YES · NO				
FREE FALL	YES · ☒ NO				
HOOK	35t, 25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2
TIRE WEAR		☒ FAIR · ☐ WORN · ☐ UNEVEN WEAR			
COMMENT					
OUTRIGGERS					
OUTRIGGERS	X · ☒ H				
OUTRIGGERS COND.	☒ FAIR · Attn				
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R	
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R	
COMMENT					
燃料エレメント付近冷却水漏れあり					
AROUND FUEL FILTER: COOLANT LEAKING					
ER103エラー表示あり(ターボ系のエラー)					
"ER103" ERROR DISPLAY FOR TURBO					
E/G小カバーなし SMALL COVER AT ENGINE HOOD: MISSING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。