

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/21	MAKE	KATO	MODEL	KRM-20H
SERIAL No.	PLATE :	7010252	STAMP :	KRC014-0252	
HR METER	12133	HR	Odometer	25912	km
TIRE SIZE	325/95R24		YEAR	2015	YR

ENGINE : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Computer	OK · NG		
Swing	FAIR · Attn		
Travel	FAIR · Attn		
TRANSMISSION			
Transmission	FAIR · Attn		
No. OF GEARS	4	GEARS	
4WD	4WD · 6WD		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
COMMENT			

BOOM					
No. of Section	6		SECTIONS		
CRACK/ENFORCEMENT	FAIR	▪ Attn			
DERRICKING CYL.	FAIR	▪ Attn			
EXTENSION CYL.	FAIR	▪ Attn			
JIB	YES	▪ NO			
JIB TYPE	STD	▪ PWR			
MAIN & SUB WIRE	YES	▪ NO			
FREE FALL	YES	▪ NO			
HOOK	20t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)					4
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR				
COMMENT					
OUTRIGGERS					
OUTRIGGERS	X	▪ H			
OUTRIGGERS COND.	FAIR	▪ Attn			
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L ▪ R
COMMENT					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。