

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE		2026/1/14		MAKE		KOMATSU		MODEL		LC503-1	
SERIAL No.		PLATE : 10033				STAMP		NOT FOUND			
HR METER		2072		HR		SHOE		400ROAD-LINER		YEAR YR	

ENGINE : MODEL 4D88E S/N 31888				INTERIOR See Photos. 写真参照			
Oil leakage		☒ FAIR · Attn		INTERIOR COND.		CLEAN · ☒ FAIR · DIRTY	
Blow-By		☒ FAIR · Attn		Operator's Seat		☒ FAIR · Attn	
Sound		☒ FAIR · Attn		Glasses		☒ FAIR · Attn	
Oil		☒ FAIR · Attn		AirCon		A/C · H/C · ☒ H only · C only · None	
Exhaust Color		☒ FAIR · Attn		UNDERCARRIAGE : See Photos. 写真参照			
OPERATION PUMP				RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3			
Sound		☒ FAIR · Attn		COMMENT			
Oil leakage		☒ FAIR · Attn					
Power		☒ FAIR · Attn					
COOLING SYSTEM				WEIGHT -			
Radiator		☒ FAIR · Attn		HOOK t数不明 TONNAGE: UNKNOWN			
Oil Cooler		☒ FAIR · Attn		FREE FALL YES · ☒ NO			
OPERATING SYSTEM				LIFTER YES · ☒ NO			
Computer		☒ OK · NG		COMMENT			
Swing		☒ FAIR · Attn		4段ブーム 4-SECTION BOOM			
Travel		☒ FAIR · Attn		CAB			
BOOM							
MAIN BOOM							
BOOM TOTAL							
TOP SHEAVE		YES · ☒ NO					
JIB							
TOWER				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。