

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/21	MAKE	TADANO	MODEL	GR-600N-2
SERIAL No.	PLATE : FE0124		STAMP : T004-0124		
HR METER	25530	HR	Odometer	67161	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · (Attn)	A LITTLE · (MIDDLE) · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Computer	(OK) · NG	3色灯不良 3-COLOR LIGHTS: MALFUNCTION
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
TRANSMISSION		
Transmission	(FAIR) · Attn	
No. OF GEARS	4	GEARS
4WD	(4WD) · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
COMMENT		

BOOM						
No. of Section	6		SECTIONS			
CRACK/ENFORCEMENT	FAIR	▪ Attn				
DERRICKING CYL.	FAIR	▪ Attn				
EXTENSION CYL.	FAIR	▪ Attn				
JIB	YES	▪ NO				
JIB TYPE	STD	▪ PWR				
MAIN & SUB WIRE	YES	▪ NO				
FREE FALL	YES	▪ NO				
HOOK	60t, 25t, BALL					
UNDERCARRIAGE : See Photos. 写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)						2
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR					
COMMENT						
OUTRIGGERS						
OUTRIGGERS	X	▪ H				
OUTRIGGERS COND.	FAIR	▪ Attn				
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L ▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L ▪ R	
COMMENT						
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。