

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/19	MAKE	KATO	MODEL	KR-50H-L2
SERIAL No.	PLATE : 4912015		STAMP : KR512-2015		
HR METER	20265	HR	Odometer	72603	km
TIRE SIZE	505/95R25		YEAR	YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Computer	OK · NG		
Swing	FAIR · Attn		
Travel	FAIR · Attn		
TRANSMISSION			
Transmission	FAIR · Attn		
No. OF GEARS	4	GEARS	
4WD	4WD · 6WD		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
COMMENT			

BOOM						
No. of Section	6 SECTIONS					
CRACK/ENFORCEMENT	(FAIR)	▪ Attn				
DERRICKING CYL.	(FAIR)	▪ Attn				
EXTENSION CYL.	(FAIR)	▪ Attn				
JIB	(YES)	▪ NO				
JIB TYPE	STD	▪ (PWR)				
MAIN & SUB WIRE	(YES)	▪ NO				
FREE FALL	(YES)	▪ NO				
HOOKE	51t, 22t, BALL					
UNDERCARRIAGE : See Photos. 写真参照						
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	3					
TIRE WEAR	(FAIR) ▪ WORN ▪ UNEVEN WEAR					
COMMENT 						
OUTRIGGERS						
OUTRIGGERS	X	▪ (H)				
OUTRIGGERS COND.	(FAIR)	▪ Attn				
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L	▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L	▪ R
COMMENT 						
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。