

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/22	MAKE	TADANO	MODEL	GR-160N-2
SERIAL No.	PLATE : 526398			STAMP : T006-0285	
HR METER	13955	HR	Odometer	76776	km
TIRE SIZE	325/95R24			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	

OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	

COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	

OPERATING SYSTEM		
Computer	☒ OK · NG	
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	

TRANSMISSION		
Transmission	☒ FAIR · Attn	
No. OF GEARS	4 GEARS	
4WD	☒ 4WD · 6WD	

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn 破れあり HUGE CUT
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None

COMMENT	

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	☒ FAIR · Attn	
DERRICKING CYL.	☒ FAIR · Attn	
EXTENSION CYL.	☒ FAIR · Attn	
JIB	☒ YES · NO	
JIB TYPE	STD · ☒ PWR	
MAIN & SUB WIRE	☒ YES · NO	
FREE FALL	YES · ☒ NO	
HOOK	16t, BALL	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	4
TIRE WEAR	☒ FAIR · ☐ WORN · UNEVEN WEAR

COMMENT	

OUTRIGGERS				
OUTRIGGERS	X · ☒ H			
OUTRIGGERS COND.	☒ FAIR · Attn			
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R

COMMENT	
過巻不良、過巻解除で操作可	
OVERWINDING PREVENTION: MALFUNCTION,	
NEED TO CUT OVERWINDING PREVENTION TO OPERATE	
燃料落ちる(手押しのポンプを押しながらE/G始動)	
FUEL PRESSURE: DROPPING	
(NEED TO PRESS THE PRIMING PUMP TO START THE ENGINE)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。