

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/19	MAKE	KUBOTA	MODEL	RX-406
SERIAL	10436		STAMP	10436	
HR METER	5202	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300G PADS	

ENGINE : MODEL		S/N	BL3044
Oil leakage	☒ FAIR • Attn		
Blow-By	☒ FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	☒ FAIR • Attn		
Oil	☒ FAIR • Attn		
Exhaust Color	☒ FAIR • Attn		
US EPA	YES • ☒ NO		
MAIN PUMP			
Sound	☒ FAIR • Attn		
Oil leakage	☒ FAIR • Attn		
Power	☒ FAIR • Attn		
COOLING SYSTEM			
Radiator	☒ FAIR • Attn		
Oil Cooler	☒ FAIR • Attn		
OPERATING SYSTEM			
Swing	☒ FAIR • Attn		
Travel	☒ FAIR • Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY		
Operator's Seat	☒ FAIR • Attn		
Glasses	☒ FAIR • Attn		
AirCon	A/C • H/C • ☒ H only • C only • None		
BOOM / ARM / BKT			
Boom	☒ FAIR • Attn		
Boom Cylinder	☒ FAIR • Attn		
Arm	☒ FAIR • Attn	ガタあり LOOSE	
Arm Cylinder	☒ FAIR • Attn		
ATTACHMENT	☒ FAIR • Attn		
BKT Cylinder	☒ FAIR • Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • ☒ WRIST
Multi	☒ MULTI • 2 • NO
ARM-CRANE	☒ YES • NO
BLADE	☒ YES • NO
OFFSET	☒ YES • NO
OFFSET Cylinder	☒ FAIR • Attn
Piping	YES • ☒ NO Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。