

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/23	MAKE	CAT	MODEL	E110B
SERIAL	9HF01925			STAMP	9HF01925
HR METER	E2619	HR	YEAR	1990	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	腐食あり CORRODED
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れ、穴あり CUTS, MUCH HOLES
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	*1
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	油漏れ小 OIL LEAKING
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	油漏れ小 OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
E/Gフード外れあり(ヒンジ破損あり) ENGINE HOOD HINGES: BROKEN	
マフラー外れ、腐食あり MUFFLER TAILPIPE: COME OFF, CORRODED	
ブーム周りホースひび割れあり HOSES AROUND BOOM: CRACKED	
CABドアラッチ掛からない DOOR LATCH: NOT WORKING	
ヒーター風出ない HEATER: NOT BLOWING AIR	
コントロールランプ点灯、ブザー音あり	
CONTROL LAMP & WARNING SOUNDS: ON	
左サイドカバーラッチ破損あり LEFT SIDE COVER LATCH: BROKEN	
HRメーターストップ HR METER: STOPPED	
*1 左側にじみ、右側油漏れあり	
*1 LEFT CYLINDER: OIL OOZING, RIGHT CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。