

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/16	MAKE	KOMATSU	MODEL	PC138US-8NM
SERIAL	32484		STAMP	KMTPC189P01032484	
HR METER	ERROR	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		4D95LE-5	S/N	572799
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタあり SWING: LOOSE	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
				None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	左右油漏れあり CYLINDERS: OIL LEAKING	
Arm	FAIR	Attn	ガタ、自然降下あり LOOSE, HYDRAULIC DRIFT	
Arm Cylinder	FAIR	Attn	油漏れあり OIL LEAKING	
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT 左右トラックローラーガタあり SOME TRACK ROLLERS: LOOSE	
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG ▪ (WRIST)
Multi	MULTI ▪ 2 ▪ (NO)
ARM-CRANE	YES ▪ (NO)
BLADE	(YES) ▪ NO
OFFSET	YES ▪ (NO)
OFFSET Cylinder	FAIR ▪ Attn
Piping	(YES) ▪ NO Breaker only ▪ (Multi)
COMMENT 本体ブームで上げたまま保持不可 UNABLE TO KEEP THE BODY AT THE PUSH-UP POSITION BY BOOM	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。