

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/1/21	MAKE	KOMATSU	MODEL	D155AX-7
SERIAL	90270	STAMP	KMT0D118KEC090270		
HR METER	4696	HR	SHOE	560G	YEAR 2014 YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER	CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE		

ENGINE : MODEL 6D140E-6 S/N 732114	
Oil leakage	(FAIR) ・ Attn
Blow-By	(FAIR) ・ Attn A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR) ・ Attn
Oil	(FAIR) ・ Attn
Exhaust Color	(FAIR) ・ Attn
US EPA	YES ・ (NO)
OPERATION PUMP	
Sound	(FAIR) ・ Attn
Oil leakage	(FAIR) ・ Attn
Power	(FAIR) ・ Attn
COOLING SYSTEM	
Radiator	(FAIR) ・ Attn
Oil Cooler	(FAIR) ・ Attn
TRANSMISSION & TRAVEL	
T/M TYPE	(PS) ・ DD DIFF. STEERING (YES) ・ NO
Transmission	(FAIR) ・ Attn
Travel	(FAIR) ・ Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY
Operator's Seat	(FAIR) ・ Attn
Glasses	(FAIR) ・ Attn
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None
BLADE & CYLINDERS	
BLADE	(FAIR) ・ Attn
CYLD.(R)	(FAIR) ・ Attn
CYLD.(L)	(FAIR) ・ Attn
TILT CYLD	(FAIR) ・ Attn
ANGLE CYLD	FAIR ・ Attn

UNDERCARRIAGE See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
Ripper MULTI ・ (S/S) Shanks 1 PCS Ripper CYLD. (FAIR) ・ Attn	
COMMENT	
ブレードチップ動作可 BLADE PITCH OPERATION (FORE-AFT TILTING): OK	
付属品: ステップ STEPS AS SPARE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。