

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/26	MAKE	KOBELCO	MODEL	SK135SR-5
SERIAL	YY08-33884		STAMP	YY08-33884	
HR METER	7953	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL		4JJ1	S/N
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	全体の動き遅い SLOW MOVING
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	
Travel	FAIR	Attn	動きが遅い SLOW TRAVELING
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None
BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2
COMMENT 右シュー1箇所、左シュー2箇所固着あり TRACK LINKS: STUCK					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG	▪	(WRIST)		
Multi	(MULTI)	▪	2	▪	NO
ARM-CRANE	YES	▪	(NO)		
BLADE	YES	▪	(NO)		
OFFSET	YES	▪	(NO)		
OFFSET Cylinder	FAIR	▪	Attn		
Piping	(YES)	▪	NO	Breaker only	▪ Multi
COMMENT A/C効かない A/C: MALFUNCTION 作動油フィルタを交換してくださいのランプ点滅あり WARNING LAMP FOR HYDRAULIC OIL FILTER REPLACEMENT: BLINKED					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。