

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/22	MAKE	HITACHI	MODEL	ZX350H-3
SERIAL	HCM1V800J00056143			STAMP	HCM1V800J00056143
HR METER	10631	HR	YEAR	2008	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		6HK1	S/N	531154
Oil leakage	☒ FAIR	Attn		
Blow-By	☒ FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR	Attn		
Oil	☒ FAIR	Attn		
Exhaust Color	☒ FAIR	☒ Attn	白煙あり WHITE FUMES	
US EPA	☒ YES	☐ NO		
MAIN PUMP				
Sound	☒ FAIR	Attn		
Oil leakage	☒ FAIR	Attn		
Power	☒ FAIR	Attn		
COOLING SYSTEM				
Radiator	☒ FAIR	Attn		
Oil Cooler	☒ FAIR	Attn		
OPERATING SYSTEM				
Swing	☒ FAIR	Attn	ガタあり SWING: LOOSE	
Travel	☒ FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	☐ CLEAN	☐ FAIR	☒ DIRTY	
Operator's Seat	☒ FAIR	Attn	破れあり CUTS	
Glasses	☒ FAIR	Attn		
AirCon	☒ A/C	☐ H/C	☐ H only	☐ C only
BOOM / ARM / BKT				
Boom	☒ FAIR	Attn		
Boom Cylinder	☒ FAIR	☒ Attn	*1	
Arm	☒ FAIR	Attn		
Arm Cylinder	☒ FAIR	☒ Attn	油漏れ小 OIL LEAKING	
ATTACHMENT	☒ FAIR	Attn		
BKT Cylinder	☒ FAIR	☒ Attn	にじみあり OIL OOZING	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / ☒ SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	MULTI · 2 · ☒ NO
ARM-CRANE	YES · ☒ NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
ブーム背面ホース破れあり HOSES AROUND BOOM: MUCH CRACKED	
A/C電源入らない A/C: UNABLE TO TURN ON	
*1 右側にじみ、左側油漏れあり	
*1 RIGHT CYLINDER: OIL OOZING, LEFT CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。