

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/20	MAKE	KATO	MODEL	KR-25H-V7
SERIAL No.	PLATE : 5115496		STAMP : KRC005-5496		
HR METER	20578	HR	Odometer	125272	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR • Attn		
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR • Attn		
Oil	FAIR • Attn		
Exhaust Color	FAIR • Attn		
OPERATION PUMP			
Sound	FAIR • Attn		
Oil leakage	FAIR • Attn		
Power	FAIR • Attn		
COOLING SYSTEM			
Radiator	FAIR • Attn		
Oil Cooler	FAIR • Attn		
OPERATING SYSTEM			
Computer	OK • NG		
Swing	FAIR • Attn		
Travel	FAIR • Attn		
TRANSMISSION			
Transmission	FAIR • Attn		
No. OF GEARS	4	GEARS	
4WD	4WD • 6WD		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • FAIR • DIRTY		
Operator's Seat	FAIR • Attn		
Glasses	FAIR • Attn		
AirCon	A/C • H/C • H only • C only • None		
COMMENT			

BOOM					
No. of Section	4		SECTIONS		
CRACK/ENFORCEMENT	FAIR	▪ Attn			
DERRICKING CYL.	FAIR	▪ Attn			
EXTENSION CYL.	FAIR	▪ Attn			
JIB	YES	▪ NO			
JIB TYPE	STD	▪ PWR			
MAIN & SUB WIRE	YES	▪ NO			
FREE FALL	YES	▪ NO			
HOOK	25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)					3
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR				
COMMENT 					
OUTRIGGERS					
OUTRIGGERS	X	▪ H			
OUTRIGGERS COND.	FAIR	▪ Attn			
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L ▪ R
COMMENT 					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。