

INSPECTION SHEET 検品書
MOTOR GRADER グレーダー

INSPECTION DATE	2025/12/11	MAKE	KOMATSU	MODEL	GD405A-2
SERIAL	4545			STAMP	G40A2-4545
HR METER	2997	HR	Odometer	-	km YEAR YR
SCARIFIER	YES	☒ NO	BLADE		3000 mm
CAB/CNP	☒ CAB	/	CNP	/	NONE
TIRE SIZE			11.00-20		

ENGINE : MODEL S/N Oil leakage ☒ FAIR · Attn Blow-By ☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound ☒ FAIR · Attn Oil ☒ FAIR · Attn Exhaust Color ☒ FAIR · Attn US EPA YES ☒ NO OPERATION PUMP Sound ☒ FAIR · Attn Oil leakage ☒ FAIR · Attn Power ☒ FAIR · Attn COOLING SYSTEM Radiator ☒ FAIR · Attn Oil Cooler ☒ FAIR · Attn TRANSMISSION & TRAVEL T/M TYPE ☒ PS · DD Transmission ☒ FAIR · Attn Travel ☒ FAIR · Attn FOOT BRAKE ☒ FAIR · Attn PARKING BRAKE ☒ FAIR · Attn INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · ☒ FAIR · DIRTY Operator's Seat ☒ FAIR · Attn Glasses ☒ FAIR · Attn AirCon A/C · H/C · ☒ H only · C only · None HYD. CYLINDER For Blade FAIR · ☒ Attn *1 For Scarifier FAIR · Attn Articulate ☒ FAIR · Attn	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 TIRE WEAR FAIR · ☒ WORN · UNEVEN WEAR COMMENT サークル旋回モーター油漏れ小 CIRCLE DRIVE MOTOR: OIL LEAKING 左側サークルリフトシリンダーにじみあり LEFT CIRCLE LIFT CYLINDER: OIL OozING ヒーター風出ない HEATER: NOT BLOWING AIR *1 スライドシリンダーメッキ剥がれあり *1 SLIDE CYLINDER: COATING PEELED RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。