

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/23	MAKE	TADANO	MODEL	TR-250M-5
SERIAL No.	PLATE : 519512		STAMP : TR253-1119		
HR METER	4727	HR	Odometer	32501	km
TIRE SIZE	445/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	FAIR (Attn)	A LITTLE · MIDDLE (SEVERE)
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	FAIR (Attn)	白煙あり WHITE FUMES
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Computer	(OK) · NG	
Swing	(FAIR) · Attn	
Travel	FAIR (Attn)	自走不可 UNABLE TO RUN ON PUBLIC ROADS
TRANSMISSION		
Transmission	(FAIR) · Attn	
No. OF GEARS	3 GEAR	
4WD	(4WD) · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
COMMENT		

BOOM					
No. of Section		4		SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn			
DERRICKING CYL.	FAIR	▪ Attn			
EXTENSION CYL.	FAIR	▪ Attn			
JIB	YES	▪ NO			
JIB TYPE	STD	▪ PWR			
MAIN & SUB WIRE	YES	▪ NO			
FREE FALL	YES	▪ NO			
HOOK	25t, 12t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)					2
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR				
COMMENT					
リアステロック不良 REAR STEERING LOCK: MALFUNCTION					
OUTRIGGERS					
OUTRIGGERS	X	▪ H			
OUTRIGGERS COND.	FAIR	▪ Attn			
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L ▪ R
COMMENT					
伸縮レバー固着あり EXTENSION LEVER: STUCK					
主巻側フック仕込んでいない MAIN WIRE: NOT ATTACHED TO ANY HOOK					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。